Kodak

FCO 512-00464A

ThermoFlex Controller Version 2.02.354.005

Document number: 719-00904A Rev A
Release date: 11 Sep 2007

Applies to all

Priority: Next failure

- Kodak® ThermoFlex® Narrow platesetters
- ThermoFlex Mid II platesetters

Component: ThermoFlex Controller software

Problems fixed

- The following error message appeared intermittently during delay and intensity (drum speed) calibration tests:

  `Emergency Stop: Drum speed deviation is above the limit.`
- Diagnostics did not work.
- During exposure, if you selected the UDRC motor through the hardware tree, the UDRC dialog box could not be closed unless you restarted ThermoFlex Controller .
- On ThermoFlex Mid II, the drum continued to revolve during media loading or unloading.
- On ThermoFlex Mid II on the operation panel, the OK button remained on intermittently.
- On ThermoFlex Mid II, after the loading process started, if the Unload button was accidentally pressed during exposure, a debug message appeared and you had to restart the ThermoFlex Controller software.

Overview

In addition to resolving the problems mentioned, version 2.02.354.005 includes the following new features and enhancements:

- Minimum drum speed is reduced is reduced to 50 rpm.
- Support for 24, 32, and 48 beams: When you install the version, you can configure the relevant number of diodes.
- Mid II Online help: The online help describes how to perform basic software tasks such as media definition, in addition to loading and unloading flexo, steel-back, and offset plates.
- File collector application: The file collector application zips the log files for improved remote support.
- On ThermoFlex Hybrid platesetters with offset option, the carriage moves to Home Position when you open the top door (Narrow) or service door (Mid II).

Time required	2 hours
Prerequisite FCOs	None

Parts included in FCO

Part Number	Part Name	Quantity
651-00811A	Version 2.02.354.005 CD ROM	1
651-00828A	FCO updater utility	1
719-00904A	FCO document	1

Tools required	N/A
Procedure	Insert the version 2.02.354.005 CD in the CD-ROM drive and proceed according to the wizard. **Note:** For more detailed information, see the ThermoFlex Controller Version 2.02.354.005 release notes on TechPlanet's Reference page.
Install FCO Tracker	Insert the diskette and double-click the reg file, or download the file from Techplanet's FCO page.
Material disposition	N/A
See also	Not applicable
Technical contact	Viki Arviv
Date submitted	11 Sep 2007
Last updated	11 Sep 2007