FCO 512-00506A: Controller Version 2.03.355.003

Internal document number: 719-01004A-A

Product

The following devices that run the Microsoft® Windows®.XP operating system:

- Kodak® ThermoFlex® Mid II
- ThermoFlex Narrow

FCO priority

Next visit

Background

- Intermittently during startup, STARTUP LOG error messages appeared in ThermoFlex Controller, and you had to restart the software.
- An error message appeared that was related to calibrating and exposing TIFF files in a resolution of 2400. To overcome this error message, the service representative built two tables (one in 94.488190 and the second in 94.487991).
- The timeout for the loading table in open mode was not long enough for the loading and unloading process, so it was lengthened to 15 minutes (instead of five minutes).
- Earlier versions did not support the Narrow S300 machines (with Omron interlocks)

Solution

Install ThermoFlex Controller version 2.03.355.003 for Windows.

In addition to resolving the problem mentioned in the Background section, version 2.03.355.003 includes the following improvements:

- Omron interlocks are supported.
- For ThermoFlex Narrow Hybrid S300, electrical balance is supported and the air pressure unit is not required.
- Online help for ThermoFlex Narrow Hybrid is included in the software.
- For ThermoFlex Mid II Hybrid with serial numbers higher than FM288, a new balance detector is supported.
- Controller generates UDRC-related messages.

Time required

One hour

Parts required

Part Number	Part Name	Quantity
651-00875A	CD Controller Version 2.03.355.003	1
651-00997A	Updater 512-00506A TFX Ver 2.03.355.003	1
719-01004A	FCO document	1

Tools required

N/A

Procedure

Insert the version 2.02.355.003 CD in the CD-ROM drive and proceed according to the wizard.

Note: For more detailed information, see the ThermoFlex Controller Version 2.02.355.003 release notes on TechPlanet's Reference page.

FCO Updater Utility

After completing the FCO procedure, insert the FCO Updater Utility CD into the CD-ROM drive and run the utility.

Technical contact	Viki Arviv
Date submitted	24 Jun 2008
Last updated	24 Jun 2008