Magnus VLF Installation Feedback Form

Site Information

Customer	Ellert Sp. z o.o.
Address	Ul. Nadrzeczna 17, 05-462 Wiązowna, Poland
Device serial number	MT221
Autoloader options installed	No

Installation Information

Installation Team	Tomasz Gogacz,
Installation start date	2.01.2007
Media type used	Kodak Electra Excel,
Media sizes used	1143x1430, 795x1050
Installation end date	11.01.2007

Problem Descriptions

Description of problems encountered	1. Emergency button was always pushed ([A2] - away site) when rear hood was closed 2. Problems with drop-leaf door 3. Safety switch and lock interlock (home site of carriage) was always open when the hood was closed 4. Problem with closing left front panel 5. Right side panel isn't closed correct 6. Problems during start up 7. Missing rear fan filters - 328-00036
Description of causes	1. It touched 2 screws under it 2. Missing magnet actuator under drop-leaf door 3. The cheater and interlock was not adjusted, 4. The caster in front of heat exchanger was wrong 5. Missing one gold support for it 6. Error about stroke clock on TH2: 03562: The stroke clock is not

	detected.
Description of solutions	1. I removed 2 shims and screws were mounted lower 2. I put new one from my box 3. I adjusted this by moving all support with interlock a little bit up and adjusted the cheater to be as lower as possible. 4. I cut the caster to be able to mount it opposite and ordered FCO CA09820 and need to be mounted. 5. I ordered this part 308-00010 and need to be mounted. 6. We upgraded Magnus to the CR 3.1 7. I ordered new filters.
Additional comments or suggestions	

Problem 4:

Before



After



Problem 5:



