Kodak

Magnus VLF
Installation Feedback Report Form

Magnus VLF Installation Feedback Form

Site Information

Customer	Inline Rollenoffset Ploch + Strube
Address	Am oberen Weidrich, 98631 Queienfeld, Germany
Device serial number	MT270
Autoloader options installed	MCU

Installation Information

Installation Team	Helge Koenig, Diethard Gersoehne
Installation start date	29.Mar.2007
Media type used	Excel HRO
Media sizes used	639x1450
Installation end date	03.Apr.2007

Problem Descriptions

Description of problems encountered	1. e45821 a slip sheet was detected beneath plate on the LT 2. fly off errors
Description of causes	1. LT Slip sheet bottom sensor 500-01135A defective 2. air pressure hoses from cylinder hits intermittent against balance weights and thereby pull the fly off sensor cable
Description of solutions	1. replaced 2. rerouted
Additional comments or suggestions	