Kodak

Magnus VLF
Installation Feedback Report Form

Site Information

Customer	Gotha Druck GmbH
Address	Gutenbergstr. 3, 99869 Wechmar, Germany
Device serial number	MT358
Autoloader options installed	APL

Installation Information

Installation Team	Helge Koenig, Matthias Pohlan
Installation start date	31.Mar.2008
Media type used	DITP Gold
Media sizes used	1165x1430x0.4, 924x1270x0.4, 1276x2070x0.4, 820x1020x.4, 690x975x0.3, 800x1040x0.3, 663x975x0.3
Installation end date	16.May.2008

Problem Descriptions

Description of problems encountered	1. Unloadtable hits against the MAB's 2. Vacuum low on fetcher 3. fetcher unexpectedly hit the away position only w.1276x2070 plates
Description of causes	1. Unloadtable not aligned in the center position regarding the MAB's 2. wrong vac. Sensor (# 10-4887a instead of # 10-4581a) was installed wrong cable (fetcher pressure sensor cable instead of ss vac sensor cable) was connected 3. fetcher away parc position has wrong parameter
Description of solutions	1. Unloadtable correct centered 2. right sensor installed + right cable connected 3. parameter corrected
Additional comments or suggestions	