Kodak

Magnus VLF
Installation Feedback Report Form

Magnus VLF Installation Feedback Form

Site Information

Customer	Bind-Rite/Union Graphics
Address	350 Michelle Place, Carlstadt, NJ
Device serial number	MT323
Autoloader options installed	MCU installed

Installation Information

Installation Team	Steve Nyktas, Tony Konior and Dmitry Koronkevich
Installation start date	October 1, 2007
Media type used	Kodak P0048 and Agfa P970
Media sizes used	589x441, 490x675, 557x720, 594x1010, 791x1029, 1143x1429, 1260x1630,1499x1981
Installation end date	October 19, 2007

Problem Descriptions

Description of problems encountered	On chiller unit, pump was running but flow control valve was shut all the way off, so no fluid was flowing to cool the head.We did not know there was a problem since this new chiller has no pressure guage or fault light.We had error when we went to image.
Description of causes	Closed flow control valve on chiller pump was closed or never adjusted from factory.
Description of solutions	We have since opened the flow valve on the pump all the way to the open position and it has been cooling the head with no problem.
Additional comments or suggestions	Other units in the field may have similar problems