Release Notes

English

Print Console

version 2.2

06-3359A-E

www.creo.com

Copyright

Copyright © 2004 Creo Inc. All rights reserved. Data subject to change without notice.

Internal 06-3359A-E

Creo and the Creo logo are trademarks or registered trademarks of Creo Inc. The Creo products mentioned in this document are trademarks or service marks of Creo Inc. and may be registered in certain jurisdictions. Apple, AppleShare, AppleTalk, EtherTalk, LaserWriter, LocalTalk, and Macintosh are trademarks of Apple Computer, Inc., registered in the U.S. and other countries. Adobe and PostScript are trademarks of Adobe Systems Inc., are registered in the U.S. Patent and Trademark Office, and may be registered in other jurisdictions as well. Acrobat, the Acrobat logo, and Adobe Illustrator are trademarks of Adobe Systems Incorporated, which may be registered in certain jurisdictions. Microsoft, Windows, and Windows NT are registered trademarks or trademarks of Microsoft Corporation in the U.S. and/or other countries. AIX, PowerPC, and RS/6000 are registered trademarks of International Business Machines Corporation. Other company and brand, product, and service names are for identification purposes only and may be trademarks or registered trademarks of their respective holders.

No copying, distribution, publication, modification, or incorporation of this document, in whole or part, is permitted without the express written permission of Creo Inc. In the event of any permitted copying, distribution, publication, modification, or incorporation of this document, no changes in or deletion of author attribution, trademark legend, or copyright notice shall be made. No part of this document may be reproduced, stored in a retrieval system, published, used for commercial exploitation, or transmitted, in any form by any means, electronic, mechanical, photocopying, recording, or otherwise, without the express written permission of Creo Inc. This document is distributed in Adobe Systems Incorporated's PDF (Portable Document Format). You may reproduce the document from the PDF file for internal use. Copies produced from the PDF file must be reproduced in whole.

Creo Inc.
3700 Gilmore Way
Burnaby, B.C., Canada
V5G 4M1
Tel: +1.604.451.2700
Fax:+1.604.437.9891

http://www.creo.com

Revised June 2004

Contents

Introduction 1

What Is in These Release Notes ... 1
Conventions Used ... 1

What Is Print Console? 2

Print Console Documentation ... 2
Supported Platforms and Operating Systems ... 2
Output Device Support ... 2

New Features 3

Processor Support for Automatic Devices ... 3
Variable Sized Media Jobs ... 3
Increase to Hot Folder Stabilization Time ... 3
Think Support ... 3

Known Problems 4

General problems ... 4
Support for Japanese extended ASCII and Mac character sets ... 4
Update known media list ... 4
New spool directory is not created if you select 'Allow cyclical hot folders' ... 4
PC crashed if exit PC while copying files to the hot folder ... 5
Bay quantity incorrect after a remake of an auto job to a manual by pass job ... 5
Deleting Non-configured Device Media Causes Print Setup and Media Size Problems ... 5
Print Console Cancels All Jobs After Select Device Color Prompt ... 5
Arrow Keys Move Cursor Two Positions Instead of One ... 5
Print Console Does Not Display SCSI Unavailable Status ... 6
New Settings Lost After Renaming or Copying Media Size ... 6
User Interface Conflict with Large Fonts Setting in Windows 2000 ... 6
Online Help Issues ... 6
Medium Number Set to Zero if Media Configured Incorrectly ... 6
Jobs With Unsupported Resolutions Not Rejected ... 6
Refreshing Queue Expands Minimized Items ... 6
Must Restart Print Console for Changes to Preferences to Take Effect ... 7
If The Device Restarts, Print Console Does Not Cancel a Device Query ... 7
Different Media Sizes in PPD Files ... 7
CTRL+G Shortcut Keys Do Not Work Consistently ... 7
Limitation to Rounding Factor for Variable Sized Media When Not Using Whole Numbers ... 7
Autoloader device problems ... 7
Auto Media Selection Option Not Supported for Automatic Devices ... 7
Next Job Shows Status of Previous Job if Previous Job Suspends During Unload ... 8
Changing Media Sizes Does Not Update the Bay Configuration ... 8
TIFF Downloader Crashes When Image Cancelled and Plate Ejected Before Next Job on VLF Trendsetter AL ... 8
Manual device problems ... 8
Using the Auto Media Selection with a ThermoFlex device ... 8
Direct Connection problems ... 8

Allow re-ordering of GDAPI jobs in the pending queue 9
Print Console Displays Constant Error Message in Brisque Direct to Trendsetter Configuration 10
Prinergy's Print Console JTP Does Not Start 10
GDAPI Jobs That Fail After Unload Not Reported in RIP 10
TIFF Connection problems 10
Invert Raster is unchecked in job properties 10
Image Problems on -ve media when Invert Raster is selected in TIFF Downloader 10
Defined TIFF Separation Color Information Displays as "Untitled" 11
Message Screen Incorrectly Indicates Job Cannot Be Remade 11
TIFF Downloader Crashes When Image Cancelled and Plate Ejected Before Next Job 11
Files Can Get Stuck in Working Folder if Using Hot Folders Without Failed and Done Folders 11
Device Not Meeting Engine Speed (for TIFF files) 12
TIFF Downloader Failing Transform Jobs 12
Add New RIP Color to Device Color Not Working Consistently 12
Copy Option on Print Setup Pane Does Not Work Consistently 12

Problems Fixed 13

Print Console Couldn't List the COM Ports 13
Print Console Installer Couldn't Create PCOperator or CreoService Accounts 13
Bay Button Issues 13
Imaging Thermal Bluelines not working (2.2.3.22) 14
Thermoflex Operator Prompts not showing 14
Brisque to Trendsetter Direct - Change SCSI poll interval to 0 during install 14
No warning message if a user tries to select other install options before installing Print Console 14
Image shift only migrates to one Print Setup if there are more than one using the same media size 14
Migration scripts and Print Console 2.2 Migration document need to agree 14
SCSI is not connected to the workstation 14
Image Artifacts caused by TIFF Downloader during transform 15
Print Console not picking up Tiff files from hotfolder 15
Remakes of read-only TIFF jobs fail 15
Add button is unavailable after choosing one separation 15
Inconsistency in proofing thickness unit of measure 15
Rounding factor set to 20mm instead of 12.7mm after upgrading from ver 2.0 16
Clean install option should not use old registry settings 16
File clipped to fit plate before manipulating any rotate or mirror option 16

Introduction

These release notes highlight the features of Print Console 2.2, and describe any known problems you may encounter. Where appropriate, these release notes refer you to the Print Console online help for more information.

What Is in These Release Notes

The release notes include the following sections:

- *What Is Print Console?*—defines Print Console, outlines the Print Console documentation set, describes interface options (GDAPI/TIFF), and lists supported devices.
- *New Features*—lists new features in this version.
- *Known Problems*—lists issues and problems that have not yet been resolved.
- *Problems Fixed*—lists problems that existed in previous Print Console software releases that have now been resolved.

Conventions Used

This section describes how fonts are used in these release notes:

Frutiger bold is used to refer to buttons and other items in a dialog box, file names, folders, menu names, and menu commands.

Minion Italic is used to refer to other chapters in the manual, book titles, and titles of other manuals.

Frutiger is used for figure and table captions.

`Letter Gothic` is used for messages on your computer screen and for information that you must type.

SMALL CAPS is used for a key or key combination on your keyboard.

What Is Print Console?

Print Console software controls output devices. It works with raster image processing (RIP) software to deliver RIPed files to an output device for imaging onto media to create digital halftone proofs, film, or plates. It interfaces with a number of workflows and RIPs and images to a number of Creo output devices.

Print Console Documentation

Print Console documentation includes:

- Print Console online help
- Print Console Quick Start Guide
- Technical bulletins for specific systems; for example, Prinergy

The Print Console online help describes Print Console concepts, dialog boxes, windows, menus, system and job configuration, and contains software procedures for managing active, pending and processed jobs through the Queues and Status windows in Print Console. The online help is available from within Print Console.

The Quick Start Guide describes fundamentals of how to use Print Console to submit jobs to the device. A PDF version of this manual is located in the \PrintConsole\pdf directory on the CD containing the Print Console software, or in the \PrintConsole\pdf folder on the drive where Print Console is installed.

The technical bulletins describe how a specific system connects to Print Console, how to configure Print Console for the system, and how to process files.

Supported Platforms and Operating Systems

Print Console is qualified for the Windows 2000 operating system (Professional edition for Dell OptiPlex workstations/Server edition for Dell 2400 and 2500 servers) running on Intel platforms.

Output Device Support

Starting with version 2.2, Print Console is now released as part of a package of output device, software, and firmware. This controlled release for any particular output device will contain only those components that have been tested and approved for that output device.

While Print Console is designed to support all output devices, please check with your Product Service Representative if you are unsure about the qualification of this version of Print Console with your output device.

New Features

This section briefly describes the new features in this version of Print Console. For more detailed information on these new features, see the Print Console online help.

Processor Support for Automatic Devices

The Device Media pane displays a dialog box indicating which processor the media is sent to. The Media Size pane has an added tab to select the processor code and rotation option.

(The processor code is the manufacturer's code for that specific type of processor).

Variable Sized Media Jobs

Print Console can apply variable or dynamically sized media to a job just before the job is imaged on the output device. Print Console displays all job's initiated with dynamic media sizes with the job's raster size listed in the Media column on the pending queue. When the output device is about to image the job, Print Console displays a message prompt requiring you to select a device medium and medium thickness, or a fixed medium size to load onto the device.

Processing jobs with dynamically sized media is especially useful when imaging hand-cut Flexo media on a ThermoFlex output device.

Note: ThermoFlex output devices do not image on the first ½" of the home side of the media. To compensate for this ½" shift, set your image template in TIFF Assembler to have a 0" home side margin and a 1" away side margin. Alternatively, you can increase the size of your media by ½". This applies to both Variable and Fixed size media.

Increase to Hot Folder Stabilization Time

The hot folder stabilization time has been modified in this version of Print Console. Print Console still waits for the file stabilization period when a new file enters the hot folder. However, if it cannot open the file after that time, it does not, at that point, fail the file; it waits for the stabilization period again and then attempts to open the file again. It repeats this step up to 100 times before sending the file the Failed folder or, if you do not have a Failed folder configured, deleting the file.

Think Support

Changes were made to the **Print Setups** pane **Imaging Mode** tab to support seamless printing. For output devices that are capable of seamless printing, enable the **Seamless Support** checkbox if you are using that feature.

Known Problems

This section lists known limitations of this version of Print Console. The problems are divided into one or more of the following sections:

- **General Problems**—lists problems that are not specific to particular devices nor workflow/RIP connections (TIFF Downloader/GDAPI). That is, these problems may manifest when driving any device and when connected to any workflow.
- **Autoloader Device Problems**—lists problems that could affect autoloading devices (devices that load and unload plates automatically).
- **Manual Device Problems**—lists problems that affect manual devices (devices that require you to manually load plates).
- **Direct Connection Problems**—lists problems for systems using the GDAPI to submit files to the device.
- **TIFF Connection Problems**—lists problems for systems using TIFF Downloader to submit files to the device.

General problems

This section describes problems that are not specific to devices or input mechanisms (TIFF Downloader/GDAPI). That is, the following problems may occur on any device connected to any workflow or RIP.

Support for Japanese extended ASCII and Mac character sets

Problem 3014

The Prinergy Team requires support for the Japanese extended ASCII character set in the filename for Prinergy version 2.1. PrintConsole, which does not support this character set, moves the tiff files with Japanese charactors in the names into the failed folder instead of the working folder.

Update known media list

Problem 3005

The known media list that Print Console uses to define media settings needs to be updated. New vendors such as Anocoil do not appear on the list. This impacts the functionality of PC with respect to value checking the GUI performs when allowing/disallowing certain functions.

New spool directory is not created if you select ‘Allow cyclical hot folders’

Problem 2461

If the 'Allow cyclical hot folders' option is selected in the Service menu, all new spool directories will not be created. It still allows you to save the new hot folder, but there is no dialog prompt to create the new spool folder.

PC crashed if exit PC while copying files to the hot folder

Problem 2841

Print Console crashes if you exit while copying files to the hot folder.

Bay quantity incorrect after a remake of an auto job to a manual by pass job

Problem 2835

After submitting an auto job with 2 separations, the job is processed and moved to the Processed queue. If you then drag the job back to the Pending queue and change the job properties to a manual by-pass job, the following happens:

- Print Console still prompts the user to load a plate manually - the bay button is blinking and the bay quantity is deducted by 2.
- The job is processed normally, but the bay button keeps blinking even though processing has finished.

Deleting Non-configured Device Media Causes Print Setup and Media Size Problems

Problem 2758

If you have print setups and media sizes that use a particular media, switch devices to a device that doesn't have that media configured, and then delete the media from the Device Media pane, you may encounter two issues:

- Media sizes using the deleted media did not have a designated device media, or could default to the next device media in the drop-down list box. In either case, Print Console does not issue any warning about the change.
- Print setups using the deleted device media change to the **Choose media just before imaging (for variable sized media)** option. Again, except for the arrow on the pane changing to red, Print Console does not issue any warning about this change.

Print Console Cancels All Jobs After Select Device Color Prompt

Problem 2258

When you submit a job that has no color designation, Print Console issues the **Select Device Color** prompt to ask you to choose a color. If you choose a color and process the job, everything works as normal. If you cancel the job, Print Console tries to process the rest of the approved jobs in the queue, but quickly fails them all for no apparent reason.

To cancel a job from the Select Device Color prompt:

1. On the Print Console Status screen, take the queue offline.
2. Cancel the job and wait for Print Console to cancel it completely.
3. When the active job clears from the Active Queue, put the queue online.

Arrow Keys Move Cursor Two Positions Instead of One

Problem 2241

The **Arrow** keys that move the cursor up and down in all Print Console queues jump two lines instead of one.

Print Console Does Not Display SCSI Unavailable Status

Problem 2764

Print Console 2.2 recognizes when the SCSI connection is broken and fails jobs with the "Job Failed in RIP" error message. However, when the SCSI connection is broken, Print Console does not change the device status to reflect this state, nor does it inform Prinergy so that it can stop sending jobs through the GDAPI.

New Settings Lost After Renaming or Copying Media Size

Problem 2587

On the Media Size pane, if you **Rename** or **Copy** a media size, and change some of the settings on associated settings, when you click **Apply**, Print Console saves the new name, but does not save the new settings.

User Interface Conflict with Large Fonts Setting in Windows 2000

Problem 2409

If you set the Windows 2000 operating system to use large fonts, Print Console may not display correctly.

Online Help Issues

Problem 2019

We have identified three issues with the Print Console online help system:

- No features on the Messages pane are currently associated with context-sensitive online help.
- In areas of the screen where Print Console groups a number of options, the context-sensitive help may appear blank. In such cases, click directly on the option that you require information about.

If you access the context-sensitive online help, you will not see the Microsoft Internet Explorer options at the top of the screen.

Medium Number Set to Zero if Media Configured Incorrectly

Problem 2283

If the media name entered in the Print Console registry does not match that set in the device (including the case), the **Medium Number in device** setting displays zero.

Jobs With Unsupported Resolutions Not Rejected

Problem 1849 (2.0)

Print Console does not always fail jobs with resolutions that are not supported by the device. For example, if you submit a job with a resolution of 1600 x 2400 dpi, the job is still processed successfully even though the head can not support output to such a resolution.

Refreshing Queue Expands Minimized Items

Problem 1892

If any items in the queue are minimized, selecting **Queue** and then **Refresh** causes those items to expand.

Must Restart Print Console for Changes to Preferences to Take Effect

Problem 1840

If you change a setting on the Preferences pane, the change may not take effect until you restart Print Console.

If The Device Restarts, Print Console Does Not Cancel a Device Query

Problem 1333 (2.0)

When running a device query, if the output device restarts, Print Console does not cancel and restart the query.

Different Media Sizes in PPD Files

No problem number

Because previous versions of the workstation software used a formula of 25.402 to convert inches to millimeters, your Print Console PPD files may reflect a 1-point difference in media sizes.

To work around this problem:

Use Print Console's equivalent of the plate matching feature in Allegro Workstation software 1.2 to adjust the matching tolerance to take the different conversion value into account.

CTRL+G Shortcut Keys Do Not Work Consistently

Problem 2523

Pressing CTRL+G normally groups jobs on the pending queue. Sometimes, however, you have to press the keys two or three times for the shortcut to work.

Limitation to Rounding Factor for Variable Sized Media When Not Using Whole Numbers

Problem 1974

The Variable Media Size option on the Print Setup pane has a limitation related to file sizes that are not whole numbers. What normally happens with this feature is that Print Console rounds the file size up, according to a pre-determined rounding factor configured on the Preferences pane, to create a new media size. However, if the either the resulting media size or the rounding factor is not a whole number, the new media size may not be correct.

Autoloader device problems

This section describes problems we encountered when Print Console drives autoloading devices (devices that automatically load and unload plates).

Auto Media Selection Option Not Supported for Automatic Devices

Problem 2534, 2533

For automatic devices, this release does not support the **Auto Media Selection** option on the General tab of the Print Setup pane due to a number of issues, such as jobs getting stuck in the working folder when submitted via a hot folder, and incorrect prompts to manually load media when driving a Platesetter.

Next Job Shows Status of Previous Job if Previous Job Suspends During Unload

Problem 2439

In all automatic devices, if a job suspends during the unload sequence, the next job in the queue displays the status of the previously suspended job. Once the suspend sequence is complete, the next job returns to its appropriate status.

Changing Media Sizes Does Not Update the Bay Configuration

Problem 2591

Print Console does not perform a consistency check on the bays to make sure the media sizes are correct. That is, if you configure a bay with a particular media size, disable the bay, edit that media size in the Media Sizes pane, and then enable the bay, Print Console does not make sure the media in the bay matches that configured in Print Console.

TIFF Downloader Crashes When Image Cancelled and Plate Ejected Before Next Job on VLF Trendsetter AL

Problem 2775

If you do the following when using Print Console to submit TIFF files to a VLF Trendsetter AL:

- cancel a job before it starts imaging (plate remains on the drum)
- submit a second job that has a different plate size (plate unloaded from device)

Print Console and TIFF Downloader may lose synchronization. Essentially, TIFF Downloader thinks the second job has been cancelled; Print Console thinks the second job is still valid. When it asks TIFF Downloader for the raster, TIFF Downloader cannot provide it and, as a result, has a break down and crashes. In the History screen, Print Console issues a `TDL` crashed on a suspended job (Invalid command (ReadyForRaster) received message.

Manual device problems

This section describes general problems we have discovered when Print Console drives manual devices (devices that require you to manually load plates).

Using the Auto Media Selection with a ThermoFlex device

Problem 2840

In the Print Setup pane, the **Auto Media Selection** on the **General** tab should be used with caution when you are using Print Console with a ThermoFlex device.

Using the **Auto Media Selection** feature may mean that you inadvertently choose the wrong media thickness. Try using **Choose Media Just Before Imaging** instead, as you can always choose the correct media thickness with this option.

Direct Connection problems

This section describes problems encountered by systems using a direct (GDAPI) to connect with a workflow or RIP. This includes systems connected to Prinergy, when outputting to a plate, and Brisque (version 4.0 only).

Allow re-ordering of GDAPI jobs in the pending queue

Problem 2628

If there is a mixture of jobs from the hot folder and GDAPI, even though they had the same priority, it won't allow you to drag the GDAPI jobs in the pending queue.

Print Console Displays Constant Error Message in Brisque Direct to Trendsetter Configuration

No problem number

In a workflow that includes Print Console 2.1, Brisque Direct and a Trendsetter output device, Print Console displays an error that the SCSI link is broken or currently unavailable when in fact there is no problem with the configuration.

To work around this problem:

1. From the Windows desktop, select **Start > Run** and type `regedit`.
2. Navigate to the following folder path:
   HKEY_LOCAL_MACHINE\SOFTWARE\Creo\PrintConsole\V2.0\ScsiConfig
3. Open the registry file **PollInterval**.
4. In the Edit DWORD Value dialog box, type `0` (zero) in the **Value Data:** box.
5. In the **Base** box, click the **Decimal** radio button.

   Note: Changes to these values will take effect while Print Console is running.
6. Click **OK** and exit Regedit.

Prinergy's Print Console JTP Does Not Start

No problem number

Print Console 2.1 only works with Prinergy version 2.0.7 and later. Previous versions of Prinergy contained an incompatible DLL that caused the Print Console JTP to fail. If you want to install Print Console 2.1 with a Prinergy system running a version before 2.0.7, you must manually upgrade the DLL in Prinergy.

GDAPI Jobs That Fail After Unload Not Reported in RIP

Problem 2155, 2538

If a GDAPI job fails during or after the unload sequence, Print Console incorrectly reports a **job complete** status to the RIP. In addition, the job may get stuck in the active queue.

TIFF Connection problems

This section describes problems encountered by systems using hot folders to submit pre-screened, 1-bit TIFF files to TIFF Downloader in Print Console. This includes systems connected to Prinergy, for proofs, and the Brisque via Screen2Go, as well as other third party workflows and RIPs.

Invert Raster is unchecked in job properties

Problem 2869

Invert Raster is unchecked in job properties even it is turned on in the printsetup. The invert flag is turned on in the registry, so it is just a GUI bug. This will be fixed in ver 3.1.

Image Problems on -ve media when Invert Raster is selected in TIFF Downloader

Problem 2791

When you are using -ve media and select the Invert Raster option in TIFF Downloader and are centering or shifting the image, output will not be as expected. The raster on the pre-image (padded or shifted area) will be inverted.

To work around this problem:

Do not use this feature when imaging to -ve media when centering or shifting image. This limitation will be corrected in a future release.

Defined TIFF Separation Color Information Displays as "Untitled"

Problem 2826

When Print Console interprets the RIP color in a TIFF separation and the approved job is processed by TIFF Downloader, the color information is lost and the color name converts to "Untitled". After the files moves to the processed queue, the color name remains "Untitled", but the device color information reflects the proper name.

This problem occurs when sending a file to be imaged on a plate, where the creator application has not written a color to a TIFF tag that TIFF Downloader interprets. When you are sending a proof, this problem does not occur.

Message Screen Incorrectly Indicates Job Cannot Be Remade

Problem 2224

When you process a job, Print Console often issues a message on the History pane indicating that the job cannot be remade. However, only jobs submitted via the GDAPI interface cannot be remade. You can remake TIFF jobs.

TIFF Downloader Crashes When Image Cancelled and Plate Ejected Before Next Job

Problem 2775

If you do the following when using Print Console to submit TIFF files to a Trendsetter VLF AL:

- cancel a job before it starts imaging (plate remains on the drum)
- submit a second job that has a different plate size (plate unloaded from device)

Print Console and TIFF Downloader may lose synchronization. Essentially, TIFF Downloader thinks the second job has been cancelled; Print Console thinks the second job is still valid. When it asks TIFF Downloader for the raster, TIFF Downloader cannot provide it and, as a result, has a break down and crashes. In the History screen, Print Console issues the message `TDL crashed on a suspended job (Invalid command (ReadyForRaster) received`.

Files Can Get Stuck in Working Folder if Using Hot Folders Without Failed and Done Folders

Problem 2761

If you are using hot folders to submit jobs, but do not have Done or Failed folders configured, jobs can get stuck in the Working folder. This only happens if you approve the jobs, but then cancel from the active queue, or when prompted to, for example, load a bay on an autoloading device.

Device Not Meeting Engine Speed (for TIFF files)

No problem number

If the device is performing a large number of retraces and is not meeting engine speed, TIFF Downloader may not be configured to send the data through the SCSI in large enough blocks.

To work around this problem:

Using the `/sws<n>` command in the **begin.inf** file, increase the block size that TIFF Downloader sends to the device. The `<n>` represents the number of bytes (in multiples of 64) that TIFF Downloader sends to the device. For example, use `/sws65536` to increase the block size to 65536 bytes (64x1024=65536 bytes). Use `/sws131072`, `/sws196608`, `/sws262144`, and so on to increment the block size.

If necessary, contact a service representative.

TIFF Downloader Failing Transform Jobs

No problem number (2.0)

If a file that has been configured with the transform option selected fails, or if it outputs with strips of data missing, TIFF Downloader may not be configured correctly.

To work around this problem:

Increase the size of the transform input buffer in TIFF Downloader **begin.inf** file. If necessary, contact a service representative.

Add New RIP Color to Device Color Not Working Consistently

Problem 1922

Normally, if you submit a proof job and map the RIP color to a device color while the **Add new RIP colors to the Proof Color Table** option is enabled on the print setup, the RIP color should be mapped to a device color for all future jobs that use that print setup. In this release, the RIP color is not permanently mapped to the device color when you select the **Add new RIP colors to the Proof Color Table**.

To workaround this problem:

Map the RIP color to the Device color on a per job basis using the Job Properties dialog box.

Copy Option on Print Setup Pane Does Not Work Consistently

Problem 2622

In some cases, the **Copy** option on the Print Setup pane does not work correctly. Specifically, if you attempt to copy two print setups, Print Console may stop you from copying the second print setup by issuing the following message: `A copy of <printsetup1> has already been made. can not create duplicate entry`.

Problems Fixed

Versions 2.2.2.2 and 2.2.5

Print Console Couldn't List the COM Ports

This problem occurred when system administrators installed Microsoft patches that tightened security on on Windows 2003 and Windows 2000 machines. This problem has been fixed.

Print Console Installer Couldn't Create PCOperator or CreoService Accounts

This problem occurred on workstations attached to a domain. When the workstations were configured to become part of a domain, they picked up the Windows password policy. The Windows password policy would not allow the creation of PCOperator and CreoService accounts. This problem has been fixed.

This fix requires new passwords. Contact a Creo service representative or check the Creo confidential document *Password Changes for Print Console Accounts* (719-00298) on TechPlanet.

Version 2.2.4

This section lists the problems from previous versions of Print Console that have been fixed in Print Console 2.2.4.

Bay Button Issues

Problem 2479, 2493, 2540

We have discovered the following issues with the **Bay** buttons when driving and automatic device:

- If the second image in a group of two suspends while the first is in the unload sequence, Print Console aborts both separations, but the bay button may continue to blink. In addition, the number of plates in the bay does not decrement until you submit the next job.
- If two bays are loaded with different media sizes and one of those bays runs out of plates, Print Console incorrectly disables it. However, if two bays are loaded with the same media sizes, when one of those bays runs out of plates, Print Console correctly keeps the bay enabled and indicates that the bay is now empty.
- In addition, if you unload one of those bays (while another has the same media size), the quantity is set back to zero. However, if only one bay was loaded (and the other was not configured at all), the quantity remains at the correct level.

Version 2.2.3

This section lists the problems from previous versions of Print Console that have been fixed in Print Console 2.2.3.

Imaging Thermal Bluelines not working (2.2.3.22)

From version 2.1
Problem 3109

Positive shifts: works only if the image stays completely on the media. If a positive shift results in the "far side" of the front getting shifted off the media, then the beginning of the backside image should be cropped, which currently is not done.

Negative shifts: does not work (unless the shift coincidentally results in the image being centred). A negative shift (which is really a crop) on the front is also applied to the back side, which is incorrect.

Thermoflex Operator Prompts not showing

From version 2.2
Problem 3004

ThermoFlex operator prompts not showing.

Brisque to Trendsetter Direct - Change SCSI poll interval to 0 during install

From version 2.1.1
Problem 2994

Print Console has a polling feature checking if the SCSI is connected to the workstation. The SCSI connected to the Brisque reports an error which results in unnecessary service calls. This is very misleading and is not an error at all.

No warning message if a user tries to select other install options before installing Print Console

From version 2.0
Problem 849

If a user selects one of the install options before installing Print Console, the installer should give a warning message and discontinue the install option.

Image shift only migrates to one Print Setup if there are more than one using the same media size

From version 2.0
Problem 2519

Image shift only migrates to one Print Setup if there are more than one using the same media size. This means that if a second print setup was associated with that plate type, there was no longer any image shift there to associate with, and so no data could be migrated.

Migration scripts and Print Console 2.2 Migration document need to agree

From version 2.2.1
Problem 2996

Migration scripts and Print Console 2.2 Migration document are not consistant - document is correct.

SCSI is not connected to the workstation

From ver 2.1.1.24 patch 2
Problem 2994

Print Console has a polling feature that checks if the SCSI is connected to the workstation. In a Direct workflow, this creates a very misleading error message that is not an error at all. The SCSI is connected to the Brisque, as it should be, but still reports the error, and is confusing and creating calls to service.

Version 2.2.2

This section lists the problems from previous versions of Print Console that have been fixed in Print Console 2.2.2.

Image Artifacts caused by TIFF Downloader during transform

From version 2.2.1.44
Problem 2985

Customer reports the image arifacts in the plate. Investigation of the problem using files provided by the customer show that Tiffdownloader is cuasing these artifacts. The problem occurs with a 2-up plate created with Tiff Assembler and when Tiffdownloader does 0 degree rotation and Mirror None.

Workflow is imposed composite PS files from Preps get sent to a Harliquin RIP. These files are RIPped to tif to a folder on the Harliquin box. This folder is then used in Print Console as a hotfolder. So the hotfolder for Print Console is across the network.

Print Console not picking up Tiff files from hotfolder

From 2.1.1.24 patch 1
Problem 2980

When TIFF files show up in the folder, they are not getting transferred to the working directory and never appear in the Print Console pending queue. When you restart Print Console, they then show up in the queue.

Version 2.2.1

This section lists the problems from previous versions of Print Console that have been fixed in Print Console 2.2.1

Remakes of read-only TIFF jobs fail

From version 2.1.1

When you submit a read-only TIFF file (for example, joba.tif) to Print Console by dropping it in the hot folder, if the job processes correctly, Print Console moves the finished job to the Done folder.

If you submit a new version of joba.tif, the job processes correctly, but the finished job does not replace the older version in the Done folder.

So, if you try to remake joba.tif, Print Console uses the old version of the file in the Done folder.

Add button is unavailable after choosing one separation

From version 2.1.x
Problem 2684

In the **Separations** tab, you can click **Add** to choose one separation only. After you have chosen a separation, the **Add** button is no longer available.

Now you can no longer add more than one separation per data source.

Inconsistency in proofing thickness unit of measure

From versions 1.0, 2.0
Problem 1635

All Spectrums - Inconsistency in proofing thickness, stored as 0.023 inches if the current unit is in inches but stored as 0.000mm if it is in millimeters.

Rounding factor set to 20mm instead of 12.7mm after upgrading from ver 2.0

From version 2.1.x
Problem 2541

If your preference in ver 2.0.1.24 was set to millimeters before upgrading to ver 2.1, the rounding factor after the upgrade is set to 20mm instead of 12.7mm (default is 0.5 inches).

This is fixed in ver 2.2 by setting the rounding factor default to 0 inches instead of 0.5 inches.

Clean install option should not use old registry settings

From versions 2.0, 2.1
Problem 2609

Trendsetter 3244 Spectrum - Communication between the workstation and output device lost after a 'clean installation'. Before doing a clean install, old registry settings had to be removed from the registry after uninstalling Print Console.

File clipped to fit plate before manipulating any rotate or mirror option

From versions 2.1.x
Problem 2786

TIFF Downloader reference guide stated that the files are clipped to fit the plate **before** manipulating any rotate or mirror options. This is incorrect. The reference guide has been corrected to state that the files are clipped to fit the plate **after** manipulating any rotate or mirror options.