FCO 512-00394A

Upgrade Magnus 400 (Manual-Quantum) Ver 1.01.391.003 to Ver 1.02.392

Document number: 719-00752A Rev B

Applies to

- Kodak® Magnus™ 400 Quantum platesetter

Priority: Next failure

Activity/Component:

- UDRC

Description

FCO 512-00394A resolves several problems that appeared in earlier versions of the software, and also includes some electronic and hardware improvements.

Time required	½ day
Prerequisite FCOs	None

Parts included in FCO

Part Number	Part Name	Quantity
UDRC		
220-01933A	UDRC BP cable	1
220-01932A	UDRC BP nozzle vacuum detector and wiring	1
344F10131	Blue polyure hose ×270 cm, OD=6 mm, ID=4 mm	1
344B25700	Straight-fit 6-to-6 mm fast connector	1

Parts (continued)

Part Number	Part Name	Quantity
Software		
651-00628A	Magnus 400 Accessories CD	1
651-00640B	Magnus 400 Version 1.02.392 CD	1
651-00674A	FCO tracker	1
719-00752A	Document—FCO 512-00393A Upgrade Magnus 400 (Manual-Quantum) Ver 1.01.391.003 to Ver 1.02.392	1

FRU after FCO implementation	See Parts list above
Tools required	Not applicable
Procedure	See Upgrading Magnus 400 Controller Software 1.01.391.003 to 1.02.392 (731-00949A).
Install FCO Tracker	Insert the diskette and double-click the reg file, or download the file from TechPlanet's FCO Updater / FCO Tracker page.
Upon completion	Not applicable
Material disposition	Not applicable
See also	Magnus 400 Controller 1.02.392.021 Release Notes (739-00328A)
Technical contact	Mario Amir
Date submitted	27 Nov 2006
Last updated	18 Jan 2007