FCO 512-00395A

Upgrade Magnus 400 (MCU-Quantum) Ver 1.01.391.003 to Ver 1.02.392

Document number: 719-00753A Rev B

Applies to

- Kodak® Magnus™ 400 Quantum
- Kodak Magnus 400 Quantum with MCU

Priority: Next failure

Activity/Component:

- MCU
- Shortcut assembly
- UDRC

Description

FCO 512-00395A resolves several problems that appeared in earlier versions of the software, and also includes some electronic and hardware improvements.

Time required 1 day

Prerequisite FCOs FCO 512-00364A Spring Spoiler for Mangus 400 (719-00698A)

Parts included in FCO

Part Number	Part Name	Quantity
MCU		
252-12897A	Slotted rubber hose	1
Shortcut Assembly		
500-04311A	Shortcut pin base-II left assembly	1
500-03874A	Shortcut pin base-II right assembly	1
500-03875A	Shortcut pin base assy-II for wide plate	2
220-01917A	Wiring (white-orange crossover)	1
196F10008	Terminal Dis F 11" #18	4

Parts (continued)

Part Number	Part Name	Quantity
UDRC		
220-01933A	UDRC BP cable	1
220-01932A	UDRC BP nozzle vacuum detector and wiring	1
344F10131	Blue polyure hose ×270 cm, OD=6 mm, ID=4 mm	1
344B25700	Straight-fit 6-to-6 mm fast connector	1
Software		
651-00628A	Magnus 400 Accessories CD	1
651-00640B	Magnus 400 Version 1.02.392 CD	1
651-00673A	FCO tracker	1
719-00753A	Document—FCO 512-00395A (MCU-Quantum) Ver 1.01.391.003 to Ver 1.02.392	1

FRU after FCO implementation	See Parts list above
Tools required	Not applicable
Procedure	See Magnus 400 Controller Software Version 1.01.391.003 to 1.02.392 Upgrade Procedure (731-00949A).
Install FCO Tracker	Insert the diskette and double-click the reg file, or download the file from TechPlanet's FCO Updater / FCO Tracker page.
Upon completion	Not applicable
Material disposition	Dispose short pins and other unnecessary MCU parts.
See also	Magnus 400 Controller 1.02.392.021 Release Notes (739-00328A)
Technical contact	Mario Amir
Date submitted	13 Dec 2006
Last updated	18 Jan 2007