FCO 512-00411A

Replace upper roller assembly with one-piece upper roller

Document number: 719-00785B Rev B

Applies to

- Kodak® Magnus™ 400
- Kodak Magnus 400 with MCU
- Kodak Magnus 400 Quantum
- Kodak Magnus 400 Quantum with MCU
- Kodak Lotem® 400 fiber head (FH)
- Kodak Lotem 400 Xpose™
- Kodak Lotem 400 Quantum

Priority: Next failure

Activity/Component:

- Upper roller assembly
- One-piece upper roller

Description

FCO 512-00411A resolves the problem of roller marks that appear on plates due to the design of the current upper roller assembly.

Time required	½ day
Prerequisite FCOs	None

Parts included in FCO

Part Number	Part Name	Quantity
252-11251A	Upper roller shaft for M400	1
358A05030	Double shield ID=7 OD=14 B=5, Class 0	2
252-11250A	Torque shaft, upper roller M400	1
500-03758A	Press arm assembly—right for M400	1
500-04562A	Press arm assembly—left for M400	1

Parts continued

Part Number	Part Name	Quantity
385U51100	Hitch pin int. d=.047" L=19/32"	1
290A2M235	L800-roller arm pin	3
651-00670A	FCO tracker	1
731-01002A-EN	Procedure—Replacing the upper roller assembly with a one-piece upper roller on Magnus 400 and Lotem 400	1
719-00785B Rev B	Document—FCO 512-00411A Replace upper roller assembly with one-piece upper roller	1

FRU after FCO implementation	Upper roller shaft Magnus 400 (part number 252-11251A)
Procedure	See Replacing the upper roller assembly with a one-piece upper roller on Magnus 400 and Lotem 400.
Install FCO Tracker	Insert the diskette and double-click the reg file, or download the file from TechPlanet's FCO Updater / FCO Tracker page.
Upon completion	Not applicable
Material disposition	Dispose the upper roller assembly.
See also	
Technical contact	Mario Amir
Date submitted	20 Nov 2006
Last updated	07 Feb 2007