Kodak

FCO 512-00441A

Xpo 3.1.42 + Update 02 for Magnus 400/Lotem 400

Document number: 719-00859A Rev A
Release date: 22 Apr 2007

Applies to

Priority: Next failure

- Kodak® Magnus™ 400 platesetter
- Kodak Lotem™ 400 platesetter
- Kodak Lotem 400 Xpose™ platesetter

Component: Xpo 3.1.42

Problems fixed

- Update 02 for Xpo 3.1.42 corrects the problem where the Xpo software stops responding after platesetter failure, and goes into a loop.

Overview

This update replaces the previous Update 01 (dated 26 Feb 2007), and provides an improved solution to the same problem.

Note: It is recommended to install the update even if the problem did not occur.

Time required Half day

Prerequisite FCOs None

Parts included in FCO

Part Number	Part Name	Quantity
651-00760A	XPO 3.1.42 +UPD 02 for Magnus 400/Lotem 400 Xpose CD (software version)	1
651-00763A	FCO 512-00441A XPO 3.1.42 +UPD 02 for Magnus 400/Lotem 400 Xpose CD (FCO Updater)	1
719-00859A	Document - FCO 512-00441A Xpo 3.1.42 + Update 02 for Magnus 400/Lotem 400	1

FRU after FCO implementation Not applicable

Tools required Not applicable

Procedure	See Xpo 3.1.42 software stops responding after device failure.
Install FCO Tracker	Insert the diskette and double-click the reg file, or download the file from TechPlanet's FCO Updater / FCO Tracker page.
Upon completion	Not applicable
Material disposition	Not applicable
See also	Not applicable
Technical contact	Mario Amir
Date submitted	22 Apr 2007
Last updated	