Kodak

Print Console

Software
Version 4.12

Release Notes
English

Internal 739-00335A-EN Rev A

Copyright

© Kodak, 2007. All rights reserved.

Kodak and Creo are trademarks of Kodak.

Acrobat, Adobe, Distiller, Illustrator, PageMaker, Photoshop, and PostScript are trademarks of Adobe Systems Incorporated.

Apple, AppleShare, AppleTalk, iMac, ImageWriter, LaserWriter, Mac OS, Power Macintosh, and TrueType are registered trademarks of Apple Computer, Inc. Macintosh is a trademark of Apple Computer, Inc., registered in the U.S.A. and other countries.

Hexachrome, PANTONE, PANTONE Hexachrome, and PANTONE MATCHING SYSTEM are the property of Pantone, Inc.

PEARL, PEARLdry, PEARLgold, PEARLhdp, and PEARLsetter are registered trademarks of Presstek, Inc.

XEROX is a trademark of XEROX CORPORATION.

http://graphics.kodak.com/

Internal 739-00335A-EN Rev A

Revised October 2007

Contents

Introduction 1

What Is in These Release Notes 1

New Features 2

Support for Magnus VLF with Automatic Pallet Loader 2

Known Problems 3

Text in recovery messages may not match the buttons offered 3

Magnus VLF with APL stops communicating 3

Introduction

These release notes describe the changes in the Print Console 4.12 software. Where applicable, the release notes refer you to other documentation for more information.

What Is in These Release Notes

The release notes include the following sections:

- *New Features* describes new menu items, options, windows, or dialog boxes that were added to Print Console software.
- *Known Problems* lists problems that are not yet resolved.

New Features

This section lists features that were added in the new release of the Print Console software.

Support for Magnus VLF with Automatic Pallet Loader

Print Console software now supports the Automatic Pallet Loader (APL) option for the Magnus VLF platesetter. The APL option can have one, two, or three segments, each with two pallet locations.

For more information about this option, see the Print Console help or the *Magnus VLF with Automatic Pallet Loader Visual Reference Guide* (653-01305A).

Known Problems

This section lists known problems in the Print Console software. If a future version of the software resolves a problem listed here, the solution will be described in the *Fixed Problems* section of the release notes accompanying that version of the software.

Text in recovery messages may not match the buttons offered

PR 11822

When an error suspends device operation, the current device state (picking plates, transporting plates, plates on drum, imaging, and so on) determines which buttons appear in the recovery message (for example, **Resume**, **Release**, **Cancel**, **Eject**).

Sometimes the instructions in the recovery message suggest clicking a button that is not available. For example, the operator may be instructed to click the **Release** button, but only **Resume** and **Cancel** are available.

Magnus VLF with APL stops communicating

PR 11900

This problem has the following symptoms:

- The device stops communicating with Print Console.
- The device stops communicating with DCAPI.
- The device stops logging in Service Shell.
- If this problem occurs during a plot, the drum slowly comes to a stop.
- The firmware may not automatically reset.

Recovery: If the device communication problem lasts longer than five minutes, cycle the power. When the device restarts, you may be prompted to remove plates from inside the device.