
Harness Wiring Diagrams
Laser Box


Drawing	**Connector**	Page
L-BOX HARNESS 1.wmf	To D box	2
L-BOX HARNESS 2.wmf	Chassis Gnd, Fans	3
L-BOX HARNESS 3.wmf	Mother board and Cold plate	4
L-BOX HARNESS 4.wmf	J2	5
L-BOX HARNESS 5.wmf	DDB Power 10 pin, Edge detect 12 pin	6
L-BOX P. S. MEASUREMENT CABLE.wmf	4 pin	7


L-BOX HARNESS 504N2D976



L-BOX HARNESS 1.wmf


L-BOX HARNESS 504N2D976 AC INPUT






L-BOX HARNESS 2.wmf

L-BOX HARNESS 504N2D976




L-BOX HARNESS 3.wmf

L-BOX HARNESS 504N2D976




L-BOX HARNESS 4.wmf

L-BOX HARNESS 504N2D976



L-BOX HARNESS 5.wmf



L-BOX P. S. MEASUREMENT CABLE.wmf