FCO #512-00236A Update 3.2 and Additions for Controller Version 1.60.09

Document number: 719-00430A-EN Rev B

Release date: 21 Feb 2005

Applies to

- Lotem® 400
- Lotem 400 Xpose

Priority: Next failure

Machines affected N/A

Component N/A

Problem

- Throughput is not optimal
- Plate separation is not optimal
- Required files and accessories are not in one central location

Solution

Update 3.2 improves throughput and plate separation, and provides one location for all required files and accessories.

Time required 1 hour

Prerequisites Lotem Controller version 1.60.09 and update 2

Parts included in FCO

Part Number	Part Name	Quantity
651-00329A	Update 3.2 CD	1
719-00430A	FCO Document	1

FRU after FCO implementation 651-00329A

Tools required N/A

Procedure

1. Close the Controller application.
2. Insert the CD in the CD-ROM drive.
3. Open the CD drive and locate the **Update 3.2** folder.
4. In the **Update 3.2** folder, double-click **setup.exe**.
5. In the Welcome dialog box, click **Next**.
6. In the following dialog box, click **Next**, and then click **Finish**.
7. In the CD drive, locate the **Additions** folder.

8. Install the relevant additional files according to the installation guidelines in the **install.pdf** file.
9. Connect power.
10. Replot to test.

Upon completion	Replot to test.
Logistics	Approved quantities:

CSC	Quantity
CAM	20
CEU	30
CAP	15
CJP	10
CMA	10

Material disposition	N/A
See also	Update 3.2 Release Note for Controller version 1.60.09
Technical contact	Mario Amir
Date submitted	21 Feb 2005
Last updated	05 May 2005