FCO #512-00221A Modified Plate Support Wheel

Document number: 719-00392A-EN Rev A

Release date: 09 Jan 2005

Applies to

MCU for Lotem® 400

Priority: **Next visit**

Machines affected N/A

Component Support wheel

Problem

When the XY bar lowers the plate for loading onto the drum, the plate hits the support wheels nearest the drum and cannot obtain the position near the drum to be loaded.

Solution

Replace the support wheels nearest the drum with the new, smaller wheels.

Time required 1 hour

Prerequisite FCOs N/A

Parts included in FCO

Part Number	Part Name	Quantity
252-08083A	Support wheel – front	5
719-00392A	FCO document	1


FRU after FCO implementation 252-80803A Support wheel - front

Tools required Hex key

FCO #512-00221A

Procedure

1. With the MCU disconnected from the platesetter and from the power, remove the hex screws that secure each small support wheel, and remove the wheel.



2. Install the new support wheels and secure them with the screws you removed in step 1.

Install FCO Tracker	Insert the diskette and double-click on the **exe** file, or download the file from TechPlanet's FCO page. For more information refer to the FAQ: FCO Tracker.
Upon completion	N/A
Logistics	Approved quantities:

CSC	Quantity
CAM	30
CEU	60
CAP	10
CJP	5
CMA	5

FCO #512-00221A

Material disposition	Dispose of small wheels
See also	N/A
Technical contact	Mario Amir
Date submitted	09 Jan 2005
Last updated	09 Jan 2005