FCO #512-00274A Release Notes for Controller Version 1.31.350.002

Document number: 719-00495A-EN Rev A

Release date: 05 May 2005

Applies to

- ThermoFlex® Mid II
- ThermoFlex Narrow

Priority: Next visit

Machines affected N/A

Component N/A

Problem

- ThermoFlex Mid II is not supported
- Diagnostics are not supported
- Remote support is not supported
- Various bugs exist

Solution

Install ThermoFlex Controller software version 1.31.350.002.
(See the Release Note for version 1.31.350.002 on the Reference page in TechPlanet.)

Time required 1 hour

Prerequisites

- Local3 board
- Strobe 7 board
- Brisque 4.1or Tiff FE 3.0.36

Parts included in FCO

Part Number	Part Name	Quantity
651-00331A	ThermoFlex V.1.31.350.002 S/W CD	1
719-00495A	FCO Document	1

FRU after FCO implementation N/A

Tools required N/A

FCO #512-00274A

Procedure

1. Close the Controller application.
2. Insert the version 1.31.350.002 CD in the CD-ROM drive, and follow the instructions in the wizard.
3. For ThermoFlex Mid II, when the software is loaded, in Regedit, locate HKEY_LOCAL_MACHINE\SOFTWARE\Scitex\Projects\LOTEMFLEXO\MACHINE and change the machine type to **LotemFlex 4048**.
   Note: This step will be eliminated with Brisque version 5.1.

Install FCO Updater utility	Insert the diskette and double-click on the **exe** file, or download the file from TechPlanet's FCO page. For more information, see FCO Updater utility.
Upon completion	Replot to test.
Logistics	Approved quantities:

CSC	Quantity
CAM	30
CEU	30
CAP	3
CJP	3
CMA	3

Material disposition	N/A
See also	Release Note for version 1.31.350.002
Technical contact	Viki Arviv
Date submitted	05 May 2005
Last updated	05 May 2005