Replacing the Cassette Plenum Rail

Document number: 512-00189A

Product	FCO priority
Magnus VLF Autoloader	Next failure

Background

The MCU cassettes are catching on the plenum rollers and are difficult to load into the MCU. The new plenum rails can be identified by the beveled edge on the side closest to the MCU.

Solution

Replace the plenum rail on all cassettes.

Parts required

Part Number	Part Name	Quantity
512-00189A	Upgrade kit	1


Procedure



Old cassette plenum rail

New cassette plenum rail

1. Open the MCU cart with the cassette loaded that needs to be upgraded.
2. Remove the existing plenum rail.



3. Install the new plenum rail.
4. Close the MCU cart and load the cassette into the MCU.

Technical contact	Martin Wight
Date submitted	01 Sep 2005
Last updated	03 Feb 2005