Magnus VLF
Installation Feedback Report Form

Site Information

Customer	Repro Team, Dreieich Germany, Customer ID 00 R 516
Address	
Device serial number	MT 095
Autoloader options installed	YES MCU

Installation Information

Installation Team	Ralf Monheim, Uwe Heckemeyer
Installation start date	27.6.2005
Media type used	Kodak HR
Media sizes used	785 x 1030, 1140 x 1410, 1165 x 1430
Installation end date	15.07.2005

Problem Descriptions

Description of problems encountered	1. After 2 Days of Operation the Status Light did not work anymore. We found the Lionel Board defective. After Replacement ok again. 2. The Ejector was touching the small right panel. We had to drill additional holes for screwing and brought the panel up a bit higher. Ok for one week, then the cover / panel sank down again and blocked the ejector for movement. Still under service.
Description of causes	
Description of solutions	
Additional comments or suggestions	