Magnus VLF
Installation Feedback Report Form

Site Information

Customer	Jungfer Druckerei und Verlag GmbH
Address	Gutenbergstr. 3, 37412 Herzberg / Germany
Device serial number	MT157
Autoloader options installed	MCU

Installation Information

Installation Team	Helge Koenig/Joerg Weigert
Installation start date	27.mar.2006
Media type used	Kodak DITP Gold
Media sizes used	
Installation end date	06.apr.2006

Problem Descriptions

Description of problems encountered	1.MCU side access door hinge broken 2.elbow on ejector cylinder broken
Description of causes	1.wrong packed, door was open 2.bad packed, ejector lay too loose in crate
Description of solutions	
Additional comments or suggestions	The press-thread-nuts on the Magnus are not tight enough and getting lost. On some places its impossible to place a regular nut. I would suggest to take some press nuts into the spare box and additionally one press-pliers (sorry, I don't know the right English word for that tool) into the installation tool box. Debris Vacuum Hose was delivered w. only 1 hose clamp