creo™

ECO/100 Label Cross Reference
Thermal Head 1.0 (Types S,S2, F, and F2)

CONTENTS

1. Introduction.....1

2. Cross Reference Table.....1

3. Marking the 100 Label.....1

1. INTRODUCTION

This document is to show the cross reference from ECO's to the number marked on the 100 label.

This document should be used for the following exposure heads:


- 32-4005: 2400 dpi, 20W
- 32-4089: 2400 dpi, 20W
- 32-4030: 3200 dpi, 20W

2. CROSS REFERENCE TABLE

Label #	ECO #	Description of change	Start Creo S/N
1	B941	Addition of desiccant box	Retrofit all machines
2	C279	Head speed increase	
3	C226	New mounting box	
4	C588	Change part number to distinguish between different speeds and mounting	
5	C939	Desiccant kit removed from Thermal head BOM	
6	D218 D277 D376	Changes to the air jet block to allow for debris removal. Changes to the shutter power sensor, mounting for reliability. Remove shroud from shutter/air jet block.	
7	E348	Changed Beam blocker to lock nut mechanism.	
8	CA01974	Airjet plate added to all TEH1.x heads.	

3. MARKING THE 100 LABEL

When marking the 100 label, use a permanent, non-water-based marker and fill in the triangle indicated (see below). Mark only the number(s) associated with the ECO(s) applied.



Note: Various optional modules may have 100 Labels with associated cross-reference document numbers.