FCO 512-00419A

Xpo 3.1.42 for Magnus 400 / Lotem 400 Xpose

Document number: 719-00804A Rev A

Applies to

- Kodak® Magnus® 400 platesetter
- Kodak Lotem® 400 Xpose™ platesetter

Priority: Next failure

Component:	Kodak Xpo™ 3.1.42 software

Problems fixed

- **Production Manager**: In the Waiting queue, you can change the order of a few jobs together, rather than changing them one by one.

Overview

Xpo 3.1.42 software introduces new features, such as the Device Remote Viewer and beam reduction, and solves problems in the previous release, such as Production Manager and MCU problems. It also supports using Magnus 400 with the LIF Rev C data board instead of the Turbo Screening Processor (TSP) board.

Time required	Half-day
Prerequisite FCOs	None

Parts included in FCO

Part Number	Part Name	Quantity
651-00687A	Xpo 3.1.42 for Magnus 400/Lotem 400 Xpose CD	1
651-00698A	FCO 512-00419A Xpo 3.1.42 for Magnus 400/Lotem 400 (FCO Updater) disk	1
719-00804A	Document—FCO 512-00419A Xpo 3.1.42 for Magnus 400/Lotem 400 Xpose	1

FRU after FCO implementation	Not applicable
Tools required	Not applicable
Procedure	See Xpo 3.1.42 for Magnus 400/Lotem 400 Xpose Installation Guide (731-00569C)

Install FCO Tracker	Insert the diskette and double-click the reg file, or download the file from TechPlanet's FCO Updater / FCO Tracker page.
Upon completion	Not applicable
Material disposition	Not applicable
See also	Xpo 3.1.42 for Magnus 400 and Lotem 400 Xpose Release Notes (739-00217D)
Technical contact	Mario Amir
Date submitted	09 Jan 2007
Last updated	