Installing the Print Console 2.0.1 Patch 1 (PC 2.0.1.25)

Context

☑ Print Console patch to support the VLF Platesetter

Background

This patch fixes a problem on found in the early production version of Print Console 2.0 (build 2.0.1.24) when driving VLF Platesetter. Specifically, when the Platesetter runs out of plates while processing a job, all Bay buttons in Print Console become inaccessible (grayed-out), and remain that way until you re-boot Print Console. To fix this problem, this patch installs a new printconsole.exe file in the PrintConsole\Bin directory.

Note: Systems using a later build (build 2.0.1.25 and later) or not driving a VLF Platesetter do not need to apply this patch.

Installing the Patch

To install this patch:

1. Close any running applications (especially Print Console).
2. Note the drive (i.e. the mapped drive letter) where the Print Console software was previously installed.
3. Create a Temp folder in the PrintConsole directory and extract all the files in the pc_201_patch_1.zip file to that folder.

   Once extracted, you should see two folders (Common and Utility), a setup.bat file, and a readme.txt file (the readme.txt is a copy of these instructions).
4. From the Temp folder, run the setup file (**setup.bat**) and follow the on-screen prompts:

   a. To proceed with installing the patch, press “y”.

   b. Enter the target drive letter (just the drive letter, no colon).

   c. Confirm your choice by pressing “y” (or press “n” to cancel).

   The installation backs up the old files to a Backup_PC201_Patch_1 directory at the root level and installs a new printconsole.exe in the PrintConsole\bin directory.
5. Press any key to continue.