ECO #: B644

Creo Products Inc.

Status: C Completed
Product: ZZZ Multiple Products Affected
Origin By: YUN LAM LI
Coordinator:
Estimate Date:
Copy Customer: N

Date Received: 5/7/97
Date Released: 6/13/97
Date Completed: 8/14/98
Implementation Cost: $0.00
Product Cost Variance: $0.00

Assigned ECR #s
B423
B429

ECO Description

A 57-4711A nut plate has been added to the VLF, CTP, TSV, and TS3 engine modules or main frames. This new nut plate prevents the nuts on the female jacks for the SCSI cable to loosen. Also included in this ECO are small B.O.M. updates to match actual production.

Part Information

Old PART ID	New PART ID	Service Code	Production Code	Reason Code
02-4189A C	02-4189A D	N/A Not Applicable	4 Future Production	4 Documentation
FG,VLF,SPARES LIST,PER CONTINENT				
11-0404A X	11-0404A Y	F Our Cost - Next	3 Work In Progress	7 Reliability
ASSY,EM,ENGINE MODULE,CTP				
11-0439C A	11-0439C B	F Our Cost - Next	3 Work In Progress	7 Reliability
ASSY,EM,MAINFRAME,TS3244				
11-0501A M	11-0501A N	F Our Cost - Next	3 Work In Progress	7 Reliability
ASSY,EM,ENGINE MODULE,VLF				
11-0502B G	11-0502B H	N/A Not Applicable	4 Future Production	6 Maintenance
ASSY,EM,CASSETTE MODULE,VLF				
11-0520B G	11-0520B H	F Our Cost - Next	3 Work In Progress	7 Reliability
ASSY,EM,WIRED FRAME,TSV				
57-4711A	57-4711A A	N/A Not Applicable	3 Work In Progress	7 Reliability
FAB,NUT-PLATE,SCSI CONN				