MCE POST Release Notes:

MCE II POST v1.03 24-Jul-2000 GKER

- Now uses "spare" J38 serial port instead of "diag" J40 serial
  port for interactive communication with the host.

MCE II POST v1.00 25-Feb-2000 GKER

- First version.
- The following tests are performed during power-on:
      9010: External SRAM test
      9001: Search for Main Firmware
  Failure of either of these tests will result in the Main Firmware
  not loading and the Service LED to be blinking the last two digits
  of the test code.
- More tests to come in subsequent releases.