


J3
TO TEE BRD

1	BLK–22	PD.LR+	
2	BLK–22	PD.LR–	
3	RED–24	+5V	1
4	WHT–24	LR.QUE/	2
5	BLK–24	GND	3
6			

TO OPTICAL
SENSOR ON
LOAD RAMP

NOTES:

1. CONNECTIONS SHOWN FROM WIRE ENTRY SIDE.
2. STANDARD TOLERANCE +20/–0 UNLESS SPECIFIED.
3. ATTACH LABEL 60mm FROM CONNECTOR END
4. EXTEND HEATSHRINK 5mm PAST END OF CABLE JACKET.
5. STRIP 30mm OF JACKET OFF OF CABLES AT BOTH ENDS.

REV	ECO	DATE	DRAWING CHANGES BY	APPROVED BY
A	C039	1997:DEC:24	R.LEVASSEUR	R.LEVASSEUR

CREO

CAB,ASSY,LRS–TEE(J3),
TS–A
ASSEMBLY DRAWING

© COPYRIGHT CREO PRODUCTS INC.

DESIGNED BY	DRAWN BY
R.LEVASSEUR	R.LEVASSEUR

MILLIMETERS UNLESS SPECIFIED	DATE	SIZE	SCALE
	1997:09:08	B	1:1

PART NO.	REV	DOC	SHEET	OF
10–3687A–A	AD	1	1	