


TO CABLE DISCONNECT ON TEE(J11)-PH

1	RED-24	+5V	1
2	WHT-24	SIG	2
3	BLK-24	GND	3

TO OPTICAL SENSOR ON LOAD RAMP MEASURING PLATE BOX

NOTES:

1. CONNECTIONS SHOWN FROM WIRE ENTRY SIDE.
2. STANDARD TOLERANCE +20/-0 UNLESS SPECIFIED.
3. ATTACH LABEL 60mm FROM CONNECTOR END
4. EXTEND HEATSHRINK 5mm PAST END OF CABLE JACKET.

REV	ECO	DATE	DRAWING CHANGES BY	APPROVED BY
A	C097	1997:FEB:10	R.LEVASSEUR	R.LEVASSEUR

CREO

CAB,ASSY,PBS-DIS, TS-A
ASSEMBLY DRAWING

© COPYRIGHT CREO PRODUCTS INC.

DESIGNED BY	DRAWN BY
R.LEVASSEUR	R.LEVASSEUR

MILLIMETERS UNLESS SPECIFIED	DATE	SIZE	SCALE
	1998:FEB:10	B	1:1

PART NO.	REV	DOC	SHEET	OF
10-3729A-A	AD	1	1	