


NOTES:

1. THIS SIDE IS SHOWN ASSEMBLED FOR CLARITY.

2. THIS CABLE IS TO BE ROUTED THROUGH THE LOAD RAMP AND CONNECTED TO THE OPTICAL SENSOR BEFORE ITEM 0020 IS INSTALLED. THE TAIL END OF THE CABLE IS TO BE ROUTED THROUGH THE SHOWN GAP AND THE REMAINING LENGTH IS TO BE BUNDLED AND ATTACHED TO THIS ASSEMBLY. NOTE THIS ORIENTATION IS FOR TS4 AND TS8. FOR TS 3/8 THE CABLE IS TO BE ROUTED THRU THE OPPOSITE END.

REV	ECO	DATE	DRAWING CHANGES BY	APPROVED BY
L	E245	2001:JULY:27	S THOMAS	S THOMAS
K	E312	2001:OCT:26	D PRIEST	D PRIEST

LATEST REV CHANGES INDICATED BY: L

ORIENTATION OF ITEM 0070 CHANGED

CREO

ASSY,MECH,LOAD RAMP, TS-AUTO TRENDSETTER 3244

© COPYRIGHT CREO PRODUCTS INC.

DESIGNED BY	DRAWN BY			
R BOUCHAL	R BOUCHAL			
MILLIMETERS UNLESS SPECIFIED	DATE 1997:JUL:07	SIZE B	SCALE 1:4	
PART NO.	REV	DOC	SHEET	OF
50-1499A — L	AD	1	1	