


DETAIL C

NOTES:

1. THIS SIDE IS SHOWN ASSEMBLED FOR CLARITY.
2. THESE CABLES ARE TO BE ROUTED THROUGH THE LOAD RAMP AND CONNECTED TO THE OPTICAL SENSORS BEFORE ITEM 0020 IS INSTALLED. THE TAIL END OF THE CABLES ARE TO BE ROUTED THROUGH THE SHOWN GAP AND THE REMAINING LENGTH IS TO BE BUNDLED AND ATTACHED TO THIS ASSEMBLY.
3. USE TWO MID-MOUNT CLAMP CABLE TIE ON THE SENSOR CABLE. SEE DETAIL C.

A	E853	2002:JUL:24	A.CHIN	S.CHEUNG
REV	ECO	DATE	DRAWING CHANGES BY	APPROVED BY

CREO

ASSY,MECH,LOAD RAMP, NEWS

© COPYRIGHT CREO PRODUCTS INC.

DESIGNED BY S THOMAS	DRAWN BY S THOMAS				
MILLIMETERS UNLESS SPECIFIED	DATE 2001:JULY:06	SIZE B	SCALE 1:4		
PART NO. 50-2426B	— A	REV AD	DOC	SHEET 1	OF 1