
REV	DESCRIPTION	DRAWN	APPROVED	DATE
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-



CAT. NO.	DESCRIPTION
507D38464	LOADING CASSETTE HADAS 200
507E38469	LOADING CASSETTE HADAS 400
507F38764	LOADING CASSETTE HADAS 800

3
2
1

SCITEX STANDARD PRODUCTION PROCEDURES

THIS PUBLICATION CONTAINS PROPRIETARY INFORMATION OF SCITEX CORP.LTD. IT IS SUPPLIED TO THOSE CONCERNED WITH THE OPERATION AND MAINTENANCE OF THE EQUIPMENT COVERED THEREIN AND MAY NOT BE DISCLOSED TO OTHERS WITHOUT THE EXPRESS WRITTEN PERMISSION OF SCITEX

UNLESS OTHERWISE SPECIFIED:

MATERIAL: - - -

FINISH: -

SURFACE ROUGH. -

SCALE 1:1

MACHINING REQUIREMENTS
BREAK SHARP CORNERS AND EDGES 0.2 MAX
FILLET RADIUS 0.4 MAX.
C'SINK INT. THREADS 90° TO MAJOR DIA
CHAMFER EXT. THREADS 45° TO MINOR DIA

GENERAL TOLERANCES:

0 ÷ 30	±0.2	HOLES 0÷10	+0.2 -0.05
30 ÷ 500	±0.3		
500 ÷ 1000	±0.5	HOLES 10+	GEN.TOL
1000 +	±1	ANGLES	±0.5°

DIMENSIONS IN MM. DO NOT SCALE DWG.
DIMENSIONS APPLY BEFORE COATING

	NAME	DATE
DRAWN	GERTI N.	26.4.95
CHECKED	EISENBERG	26.4.95
DESIGNED	I. LASKAR	13.12.94
CHECKED	I. LASKAR	30.4.95
APPROVED	-	-
PROD.ENG	-	-
MFR.ENG	-	-
Q.A.	-	-

scitex

LOADING CASSETTE HADAS200/400/800

CAT.NO. SEE TABLE

SHEET 1 OF 1

732E26349 1

DWG. NO. REV