Appendix D: Required Update for Spectrum platesetters



Important: Spectrum platesetters will only expose proofs when the following procedures have been completed.

1. Open Service Shell.
2. Type the following command:
   `Quantum>>`**access dev**
   `Quantum>>`**option**

   Note: Ensure that the Spectrum option is enabled.

EdgeDetect option is	enabled
Spectrum option is	**enabled**
Debris UDRCB option is	disabled
Debris UDRCL option is	disabled

   If the Spectrum option is disabled, type the following command:
   `Quantum>>`**option spectrum enable**
   `Quantum>>`**reset**
3. Type the following command:
   `Quantum>>`**set proof 1 name "proof"**

   Note: Implement this command to successfully plot a proof. This command will only work on Spectrum platesetters. An error message will be generated on non-Spectrum platesetters.