Kodak

Magnus VLF
Installation Feedback Report Form

Site Information

Customer	Intermediaprint GmbH
Address	Dreieichstrasse 4, 64546 Moerfelden-Walldorf, Germany
Device serial number	MT342
Autoloader options installed	Semi auto

Installation Information

Installation Team	Gerry Ehret, Ralf Monheim, Thomas Werner
Installation start date	18. December 2007
Media type used	Kodak Electra Excel HRO
Media sizes used	480 mm X 669 mm,914 mm X 1166 mm
Installation end date	10. January 2008

Problem Descriptions

Description of problems encountered	Cooling fluid leaking at heat exchanger reservoir CFL license missing
Description of causes	Loose nut holding fitting Customer changed configuration two times!!
Description of solutions	Tighten nut Used emergency license, until correct license was available
Additional comments or suggestions	