Installing the Diagnostic Cable Bracket

Applies to ThermoFlex, prior to FX36

Background Head focus problems may occur if the head diagnostic cable that is mounted inside the machine is not grounded. A bracket is being factory installed on all machines from FX36 on, but should also be field installed on any earlier machine that has head focus problems.

Tools and parts

- Diagnostic cable bracket 57-9559A
- Loctite 242

Steps

1. Attach the bracket to the power box, as shown in Figure 1.
   Use the existing M6 screw; apply Loctite when reattaching it.




Figure 1: Power box with diagnostic cable bracket attached

Notes

Technical contact Derrick Huber

Date submitted 13 February 2002

Date modified