
# Plate Exposure and Processing Variables

## Platesetter/Trendsetter



**Exposure**
- Focus
- Laser power
- Drum speed


## Pre-heat oven



**Temp.**
- Too high - Fogging
- Too low - Areas washed out or banding

**Conveyor Speed**
- Too high - Areas washed out or banding
- Too low - Fogging

## Processor



**Transport Speed**
- Too high - Fogging
- Too low - Areas washed out or banding

**Developer Temp.**
- Too low - Fogging
- Too high - Areas washed out or banding & reduced life of developer

**Developer Replenish Rate**
- Too high - Waste of chemistry
- Too low - Reduced life of developer - eventually leading to fogging

**Developer Age**
- Too old - Fogging

## Variables