# 199D50465 ULTRA VHDCI 68 TO HPDB 68 ,1.5M

The cables are the same and you can tell the difference between them by the screws on the connectors.
The good cables have steel screws on the connectors (picture 2) while the faulty cables use black plastic covers (picture 1) on the connectors.

**Picture-1**




**Picture-2**

