
Matchprint Virtual Quick Reference Card

Download and install the *Kodak Matchprint* Virtual calibration software from http://**graphics.kodak.com/matchprintvirtual/**.

Monitor Calibration


Before calibrating, ensure that the monitor has been on for at least one hour.

1. From the Dock on your *Macintosh* computer, click the **MATCHPRINT Virtual** folder. Select **MVP Calibrate System**.




2. Place the colorimeter face down on a flat, opaque surface so that no light enters the sensors. Click **OK**.

Wait several seconds. When the colorimeter is ready, the monitor screen turns black. A template appears.



3. Place the colorimeter directly over the template and click any key.



The calibrator must rest flat against the screen.
Do not move the calibrator while the monitor is being calibrated.

A series of color patches appears as the colorimeter takes measurements.

Monitor calibration may take about 10 minutes. When calibration is complete, this message appears:

```
Calibrate System on this monitor passed.
Color Verification:
Luminance:
```

4. Record the luminance value displayed in the message and click **OK**.

- If you have a single monitor, this message appears:

```
Calibration of this system was completed.
1 monitor passed calibration.
```

- If you have a dual-monitor system, the screen of the second monitor is now black. A template appears. Repeat Steps 3 and 4 for the second monitor. When calibration is complete, this message appears:

```
Calibration of this system was completed.
2 monitors passed calibration.
```

5. Click **OK**.

6. Remove the colorimeter from the monitor.

Troubleshooting: If calibration fails, close the *Matchprint* Virtual calibration software and repeat the procedure. If calibration continues to fail, contact your printer for assistance.

© 2006 Kodak. All rights reserved.

732-00038B-EN Rev A
May 2006